

PHOTOGRAPHIC DOCUMENTATION AND OBSERVATIONS REPORT

DATE: February 22, 2011

OBSERVATIONS MADE BY: Karen Jurist, USEPA Region 9

SITE: Jervis B. Webb Co.

EPA ID: CAD008339467



Photograph 1: Jervis facility, currently occupied by Reliable Steel. Cracks in the pavement containing vegetation are seen in the center and along the left border of the photograph. Due to the poor condition of the pavement, precipitation could infiltrate the contaminated soil beneath.



Photograph 2: Jervis facility, currently occupied by Reliable Steel. Cracks in the pavement containing vegetation are seen in the center of the photograph and in the warehouse entrance. Due to the poor condition of the pavement, precipitation could infiltrate the contaminated soil beneath.



Photograph 3: Jervis facility displaying areas of the site where there is no pavement. Pooled water is visible in the bottom left corner of the photograph.